

## MOUNTING INSTRUCTIONS FOR C3SCGY AND C4XSCSS

### PARTS LIST:

ITEMS #	PART NUMBER		QTY.
	C3MTGFOOT	C4XMTGFOOT	
1)	MOUNTING FOOT ZP	MOUNTING FOOT 304SS	4
2)	SEALING WASHER GALV.	SEALING WASHER GALV.	4
3)	3/8 - 16 BOLT ZP	3/8 - 16 BOLT 304SS	4
4)	3/8 - 16 NUT ZP	3/8-16 NUT 304SS	4

Mountain kits are required to maintain marked Type rating.

Part No.	Material
C3MTGFOOT	Zinc Plated Mild Steel (Type 3, 12 and 4)
C4XMTGFOOT	Type 304 Stainless Steel (Type 3, 12 and 4X)

### INSTRUCTIONS:

- 1) To mount enclosure drill (4) x 0.500" holes at each corner as shown in Fig 1.2.
- 2) Ensure mounting surfaces are flush. Shim surfaces if required.
- 3) Install mounting hardware as shown in Fig 1.3. Ensure rubber side of sealing washer is facing enclosure.
- 4) Torque to 180 IN-LBS. Washer should remain flat against enclosure surface see Fig 1.1. Incorrect usage of sealing washers may cause leakage.

FIG 1.1

